







Project Need and Current Conditions

- The bridge is well past it's prime and is starting to show signs of wear.
- Bridge deck is cracking
- The concrete on the deck underside crumbling
- Steel beams are starting to show wear







Current Conditions

 Arapahoe Road narrows down from both directions before crossing the bridge





Current Conditions


- Lack of adequate pedestrian facilities
- Staircase is the only access to Big Dry Creek Trail








Proposed New Bridge Section












- Current median prohibits traffic access to the dual left-hand turn lanes, which causes backups on the insides through lane.
- The narrower median will allow earlier access traffic turning onto southbound University Boulevard.







New Trail Connection to Big Dry Creek










Draft Rendering of Preliminary Design (subject to change)





Project Schedule











Next Steps

Public Comment Card:

https://www.surveymonkey.com/r/ArapahoeRoadBridge

Project Website: centennialco.gov/roadprojects

> City of Centennial: Art Negretti, PE **Engineering Manager** anegretti@centennialco.gov





